

ASSET FINANCE
CORPORATION



2018 METSO LT300GP Cone Crusher



ASSET FINANCE CORPORATION



Metso LT300GP Mobile Cone Crusher

High-Capacity Secondary Crushing | Mobile Versatility | Proven Metso Performance

Location: Benoni

Hours: 8454

Overview

- **Model:** Metso Lokotrack LT300GP
- **Type:** Mobile Cone Crusher (Track-mounted)
- **Application:** Secondary and tertiary crushing in aggregates, mining, and recycling
- **Known For:** Efficient GP300S cone, high productivity, and mobility

Why the LT300GP?

- High-capacity secondary/tertiary crushing in one mobile unit
- Easy transport and fast setup for on-site operations
- Reliable Metso GP cone technology with wear part availability
- Efficient power-to-weight ratio and fuel economy
- Ideal for high-volume, quality-focused aggregate production

Finance available on this machine. Contact our expert team today.



LT300GP Tech Specs

- Each track is powered by an automatic two-speed shift travel motor.

Engine	CAT	C15
Engine Power	M	403
Crusher	Nordberg	GP330
Operational Weight	Kg	43000-50000
Conveyor Discharge Height	M	3,6
Crushing Capacity	Ton	500 tph

Transport

Height	M	3,6
Length	M	17,2
Width	M	3,4
Weight	Kg	43,000
Weight	Kg	50,000

Features

Proven GP300S cone with optimized stroke and speed

Fully hydraulically adjustable CSS (closed side setting)

Integrated screen option for closed-circuit crushing

Smart operation via **IC™ process control system**

Large hopper and feeder

Ideal for multi-stage crushing or stand-alone use

Massive stockpiling capacity

Fast setup and teardown time

Fully tracked for maneuverability on-site

Remote control for mobility and safety



Work Done

- Crusher completely rebuilt, incl. Cone concave liner, Cone mantle and liners
- Crusher input shaft completely rebuilt and backlash set to OEM spec
- Generator/alternator rewired
- Feed conveyor belt and idlers repaired and or replaced
- Discharge conveyor belt and idlers replaced
- Major service done
- New alternator and batteries installed
- New lubrication pumps installed
- Full hydraulic service completed
- Electrical contactors replaced and all systems checked
- Receiving chute repaired
- Discharge chute repaired
- Feed chute repaired



ASSET FINANCE CORPORATION

Office - 011 467 2990

(Sales & Finance) Mkhize Buso - 084 332 2464

(Technical) John Young - 082 777 1536

(Sales & Finance) Louis Lizemore - 066 243 2682

info@assetfincorp.co.za www.assetfincorp.co.za